

Analysis of the T63-A-700 Engine used in Alcohol Turbine Fuel Extender Test

John S. Glaeser
Depot Engineering and RCM Support Office
U.S. Army Aviation Systems Command
Naval Air Station, Corpus Christi, Texas

August 1990

DOT/FAA/CT-TN90/18

Document is on file at the Technical Center
Library, Atlantic City International Airport, N.J. 08405



U.S. Department of Transportation
Federal Aviation Administration

Technical Center
Atlantic City International Airport, N.J. 08405

NOTICE

This document is disseminated under the sponsorship of the U. S. Department of Transportation in the interest of information exchange. The United States Government assumes no liability for the contents or use thereof.

The United States Government does not endorse products or manufacturers. Trade or manufacturers' names appear herein solely because they are considered essential to the objective of this report.

1. Report No. DOT/FAA/CT-TN90/18	2. Government Accession No.	3. Recipient's Catalog No.	
4. Title and Subtitle ANALYSIS OF THE T63-A-700 ENGINE USED IN ALCOHOL TURBINE FUEL EXTENDER TEST		5. Report Date August 1990	
		6. Performing Organization Code	
7. Author(s) John S. Glaeser		8. Performing Organization Report No. DOT/FAA/CT-TN90/18	
9. Performing Organization Name and Address Depot Engineering and RCM Support Office U.S. Army Aviation Systems Command Naval Air Station, Corpus Christi, Texas		10. Work Unit No. (TRAIS)	
		11. Contract or Grant No.	
12. Sponsoring Agency Name and Address U.S. Department of Transportation Federal Aviation Administration Technical Center Atlantic City International Airport, NJ 08405		13. Type of Report and Period Covered Technical Note	
		14. Sponsoring Agency Code ACD-210	
15. Supplementary Notes COTR: Augusto Ferrara			
16. Abstract The teardown analysis of the T63-A-700 engine used in fuel extender research at the Federal Aviation Administration (FAA) Technical Center was conducted by the United States Army Aviation Systems Command (AVSCOM) Depot Engineering and Reliability Centered Maintenance Support Office (DERSO) in order to assist the FAA in completing an evaluation of the use of alcohols as extenders for the existing turbine fuels. The turbine section of the T63-A-700 engine displayed burned vanes on the first stage gas producer. In addition, the blade tips of the second stage gas producer turbine rotor had rubbed the interior of the second stage gas producer nozzle. It was concluded that the vanes on the first stage gas producer burned during a series of hot or hung starts using extender fuels. The inefficiency of both the fuel nozzle and the fuel control unit using alcohol blends during starting operations caused the overtemperatures. The second stage gas producer nozzle was warped as a result of thermal cycling from ambient temperature to a hot or hung start condition that caused the turbine rotor tips to rub the nozzle. The remainder of the engine, including the seals, fuel control unit, fuel nozzle, bearings, and internal components, showed no discrepancies. Much of the change appears to have resulted from hung starts. Future evaluations of extender fuels should consider using design fuels during starting operations and then introducing extender fuels after the engine has reached normal operating conditions.			
17. Key Words Alternate Fuels, Alcohol, Turbine Engine, Teardown, Inspection		18. Distribution Statement Document is on file at the Technical Center Library, Atlantic City International Airport, New Jersey 08405	
19. Security Classif. (of this report) Unclassified	20. Security Classif. (of this page) Unclassified	21. No. of Pages 16	22. Price

ACKNOWLEDGEMENTS

The technical assistance provided by the following AVSCOM and CCAD personnel was invaluable in completing this report:

Ed Ledwig	AVSCOM Engine Technology Section
Joe Stephens	
Jesus Vela	AVSCOM Technical Management Section
Ed Wilson	CCAD Engine Pre-Shop Analysis Section
Charles Warren	CCAD Analytical Investigation Branch
Norman Brinker	CCAD Metallurgical Branch

TABLE OF CONTENTS

	Page
EXECUTIVE SUMMARY	vi
INTRODUCTION	1
VISUAL INSPECTION	1
TEST CELL	2
TEARDOWN	2
ENGINEERING ANALYSIS	3
CONCLUSIONS	3

LIST OF ILLUSTRATIONS

Figure	Page
1 Fuel Consumption Comparison	5
2 Output Power Comparison	5
3 The Affected Trailing Edges	6
4 Trailing Edge Showing Incipient Melting	6

LIST OF TABLES

Table	Page
1 Performance Ratings	7
2 Gas Turbine Engine Test Log Sheet	8
3 Leading Particulars	10

EXECUTIVE SUMMARY

The teardown analysis of the T63-A-700 engine used in fuel extender research at the Federal Aviation Administration (FAA) Technical Center was conducted by the United States Army Aviation Systems Command (AVSCOM) Depot Engineering and Reliability Centered Maintenance Support Office (DERSO) in order to assist the FAA in completing an evaluation of the use of alcohols as extenders for the existing turbine fuels.

The turbine section of the T63-A-700 engine displayed burned vanes on the first stage gas producer. In addition, the blade tips of the second stage gas producer turbine rotor had rubbed the interior of the second stage gas producer nozzle.

It was concluded that the vanes on the first stage gas producer burned during a series of hot or hung starts using extender fuels. The inefficiency of both the fuel nozzle and the fuel control unit using alcohol blends during starting operations caused the overtemperatures.

The second stage gas producer nozzle was warped as a result of thermal cycling from ambient temperature to a hot or hung start condition that caused the turbine rotor tips to rub the nozzle.

The remainder of the engine, including the seals, fuel control unit, fuel nozzle, bearings, and internal components, showed no discrepancies.

Much of the change appears to have resulted from hung starts. Future evaluations of extender fuels should consider using design fuels during starting operations and then introducing extender fuels after the engine has reached normal operating conditions.

INTRODUCTION

The Federal Aviation Administration (FAA) Technical Center evaluated the performance of alcohol as extenders for the existing aviation turbine fuels. The evaluation, which was conducted at the FAA Technical Center dynamometer facility, used a T63-A-700 engine. The engine used in this project was loaned to the FAA by the United States Army Aviation Systems Command (AVSCOM).

Various experimental fuel blends were evaluated in the T63-A-700 static test cell tests. These blends consisted of either ethanol or methanol mixed with either JP-4 or Jet-A, and the alcohol concentration varied from 5 to 20 percent. The engine accrued approximately 120 total hours during the evaluation.

It was decided that a teardown analysis of the engine would not be performed at the FAA facility in Atlantic City, NJ. The engine was shipped to the Corpus Christi Army Depot (CCAD) after completion of the evaluation.

The AVSCOM Depot Engineering and Reliability Centered Maintenance Support Office (DERSO) assisted the FAA in the final evaluation. DERSO is collocated with the CCAD complex at the Naval Air Station, Corpus Christi, TX. DERSO assigned a project engineer to conduct the teardown analysis of the engine.

A four-point project plan to complete the engine teardown analysis was developed. It included a visual inspection, a test cell run to determine the operating characteristics, a complete teardown inspection to determine failure modes of internal components, and an analysis of all internal engine and fuel control unit seals for deterioration. Emphasis was placed on the engine hot (turbine) section and the fuel system. Funds for this project were limited and allowed no additional analysis.

VISUAL INSPECTION

The T63-A-700 engine, serial number AE403067BCD, was inspected at the CCAD Engine Pre-shop Analysis Section to insure that the engine was test-cell ready. The hot section of the engine displayed a carbon/exhaust buildup on the exterior of the engine case. This buildup is suspected to be from hot or hung starts resulting from use of the alternate fuel mixtures.

The fuel system had been modified to include a T-fitting in the fuel line prior to the fuel control unit. This modification was used for fuel pressure measurements. The engine turbine section rotated freely by hand and exhibited no binding or rubbing. Therefore, the engine was transferred to the test cell for an operational test.

TEST CELL

The fuel used during this test run was MIL-J-5624, JP-4.

The engine was placed in test cell number 9. Pre-test troubleshooting revealed that the ignition exciter was inoperable. A serviceable exciter was installed, and the engine started normally.

The engine oil consumption during the test cell run was normal.

The specific fuel consumption for the engine was consistently higher than the maximum allowable (figure 1).

Extrapolation of the test cell data indicates that the engine will produce rated power at 105 percent N1 speed, 1484 °F turbine outlet temperature, and 93.5 foot-pound-force (ft·lbf) torque, when corrected to standard day, sea level conditions. Obviously, the engine was not run in the test cell at these conditions as the maximum operating temperature was 1380 °F (table 1).

The engine was operated through all ranges of power settings. Table 2 reflects the test run parameters. At all power settings, the shaft horsepower (referred to standard day, sea level conditions) was lower than the minimum specified in TM55-2840-231-23, Aviation Unit and Intermediate Maintenance Manual, Engine Assembly (figure 2).

TEARDOWN

After the functional test, the engine was transferred to the CCAD Engine Pre-Shop Analysis Section area for teardown analysis. The fuel control unit and the fuel nozzle were transferred to the CCAD Fuel Control Shop for analysis.

The engine disassembly revealed several discrepancies in the hot section. The first stage gas producer nozzle vanes had burned trailing edges. One 3-vane section of the nozzle was burned more heavily than the remainder of the vanes (figure 3).

The second stage gas producer turbine rotor blade tips had rubbed the top and bottom of the second stage gas producer nozzle cylinder. Dimensional checks were conducted on the gas producer nozzle. The only discrepancy was the flatness of the forward flange face which is adjacent to the cylinder. When the faces were measured on a flat measuring table, one face of the nozzle flange was found to be 0.006 inch high. This is an indication of nozzle warpage. The high point was located 90 degrees from the rubbed areas of the cylinder.

The number eight bearing had some discoloration, which indicated some slight overheating in the gas producer section of the turbine assembly.

The fuel control components were all in working order. The fuel control seals had no evidence of deterioration. The fuel nozzle was clean and showed no discrepancies which would have altered the fuel atomizing pattern.

The remainder of the engine components displayed no defects.

ENGINEERING ANALYSIS

First stage gas producer nozzle - The nozzle was analyzed at the CCAD Metallurgical Laboratory. An examination of the burned cross-section confirmed incipient melting in this area of the nozzle (figure 4). The number of engine hours at the time the nozzle started to burn is unknown. The type of fuel in use and the engine operating parameters when this failure commenced is also unknown; however, the following hypothesis is probable. The inspection of the fuel nozzle and the fuel control unit installed in this engine revealed that they were operating normally. The fuel atomization pattern for this nozzle was proper for normal operating conditions. However, the alcohol fuel mixtures may have altered the flame pattern during starting and low power requirements, particularly during hot and/or hung starts. In addition, the flame speed when operating on alcohol fuels is slower, and it is possible the flame front extended beyond the burner can. This further compounds the overtemperature problem during a hot or a hung start.

Second stage gas producer nozzle - The dimensional check of the nozzle indicated warpage at a point 90 degrees from the rotor tip rub marks. The rub marks were 180 degrees apart and were uneven in length and depth. This would confirm warpage at only one point on the nozzle as measured in the laboratory. The cause for the nozzle warpage was most likely due to higher than normal starting temperatures from the alcohol blends and was aggravated by the burned nozzle vanes during starting. Thermal cycling from ambient temperatures to a start or hot start condition may have contributed to the warping. A portion of the vanes also burned away. Heat transfer between the vanes and the perimeter of the nozzle increased allowing a more rapid thermal cycle to the unit.

Second stage gas producer turbine rotor - The blade tips of the rotor had rubbed the second stage nozzle due to the warpage and elliptical shape of the nozzle itself. The rotor blade tips were worn due to the rubbing. This rubbing effect may have resulted in hung starts until the blades tips had worn and the nozzle gouge was deep enough to allow freewheeling of the turbine in the nozzle.

CONCLUSIONS

The behavior of the engine in the test cell run (low shaft horsepower and high specific fuel consumption) was confirmed during teardown and analysis and revealed the inefficiency of the burned first stage gas producer nozzle vanes.

It is probable that the ethanol and methanol blends with jet fuel influenced the efficiency of both the fuel control unit and the fuel nozzle, particularly during engine starting operations.

It is unknown how or when the first stage gas producer nozzle was exposed to temperatures high enough to burn the nozzle vanes. The engine analysis indicates that some combination of blended fuels and a hot or hung start precipitated the problem.

It is also unknown what effect the damaged hot section had on the results of the evaluation itself. It is possible that consistent reproducibility of the evaluation results were affected after the hot section of the engine became damaged.

Assuming that the alcohol blends contributed to the hot section damage during starting operations, it follows that consideration should be given to using only jet fuel to start gas turbine engines. Extender fuels would be introduced after the engine reached normal operating conditions. This would require additional testing to confirm the above assumption. The Federal Aviation Administration Technical Center reported that the incidence of hung starts was reduced by starting the test engine on either neat Jet-A or neat JP-4.




FIGURE 1. FUEL CONSUMPTION COMPARISON




FIGURE 2. OUTPUT POWER COMPARISON



FIGURE 3. THE AFFECTED TRAILING EDGES




FIGURE 4. TRAILING EDGE SHOWING INCIPIENT MELTING

TABLE 1. PERFORMANCE RATINGS (STANDARD SEA LEVEL STATIC CONDITIONS)

Rating	Shaft HP (min)	Net jet thrust lb (min)	Gas producer speed rpm (%) (est)	Output shaft rpm	Specific fuel consumption lb/SHP-hr (max)	Ram power rating torque at output shaft ft-lb (max)	Measured rated gas temp °F (°C) (max)
Takeoff	317	33	51600 (100.9)	6000	0.697	293	1380 (749)
Normal	270	28	49760 (97.3)	6000	0.706	249	1280 (693)
90% normal	243	26	48650 (95.2)	6000	0.725	249	1226 (663)
75% normal	203	21	46950 (91.8)	6000	0.762	249	1148 (620)
Start and idle	35 max	10 max	32000 (62.6)	4500-6300	61 lb/hr	—	750 ± 100 (399 ± 56)
Flight auto- ration	0 max	10 max	32000 (62.6)	5900-6480	61 lb/hr	—	725 ± 100 (385 ± 56)

NOTE: Specific fuel consumption = fuel flow/SHP.

TABLE 2. GAS TURBINE ENGINE TEST LOG SHEET

RIN-102RJ30024Z

PRINTED 11/01/79 07:53:57 PAGE 1 OF 2

TEST ACTIVITY				SER. NO. AE403067BCD				STAND NO. 09				PRE-OIL				90010 OPERATORS				STARTING				COMPLETING											
CORPUS CHRISTI ARMY DEPOT				SER. NO. 090Y.0021				TEST NO. 1				IN-PROCESS				90010				CHUPE/U.				MUNSON/P.F.											
CORPUS CHRISTI, TEXAS				TYPE/MOD. I43-A700				RUN TIME				A-34				INSPECTOR NUMBER				HOWARD/B.J.				MARTINEZ/G./JR.											
TYPE TEST- MINOR																																			
POWER SETTING				GI				44.0				61.5				75.0				90.0				100.0				100.0				T/O			
RUN MODE				A				A				A				A				A				A				A				A			
TIME OF DAY				0933				1629				1635				1640				1644				1647				1650				1654			
ELAPSED TIME				00				16				106				105				104				106				103				138			
N1 SPEED				62.6				65.1				68.4				71.9				74.9				77.3				79.0				101.1			
N1 SPEED REF				84.4				87.7				91.1				94.2				96.6				98.2				100.3				100.3			
N2 SPEED				79.7				100.0				100.0				100.2				100.0				100.2				100.0				100.1			
LOAD				120				970				1300				1630				1750				2240				2430				2690			
SHP MAXIMUM								106				151				197				243				277				312				336			
SHP ACTUAL				9				93				124				156				186				211				232				257			
SHP REFERRED								92				122				154				183				208				229				253			
MGT ACTUAL				820				999				1073				1147				1228				1279				1327				1370			
MGT REFERRED								974				1050				1119				1202				1252				1296				1350			
COMP IN-TEMP				63				60				67				68				67				67				68				67			
OIL IN TEMP				217				211				211				209				198				197				196				196			
OIL OUT TEMP				224				228				249				235				234				237				239				241			
FUEL IN TEMP				66				63				63				63				63				63				63				64			
TORQUEMETER				4.3				28.2				36.8				45.7				55.2				62.3				68.5				75.9			
GEARBOX PRESS				.5				2.8				3.7				3.7				3.9				3.5				4.1				4.1			
OIL IN PRESS				.0				.6				.7				.6				.6				.6				.6				.6			
OIL SCAV PRESS				25.9				32.1				31.7				32.5				33.1				33.0				33.3				33.5			
OIL PUMP PRESS				71.5				122.4				123.4				127.6				127.7				127.6				127.4				127.1			
FUEL IN PRESS				32				29				20				20				20				20				20				20			
BAROMETER				30.51				30.22				30.23				30.23				30.23				30.23				30.23				30.22			
BLEED EXH TEMP				107				80				101				89				82				84				83				81			
BLEED-REF-TEMP				67				71				62				72				72				72				73				72			
COMP SEAL VENT PR				5.01				5.37				5.63				5.75				5.63				5.19				3.98				4.23			
ANTI-ICE AIR TEMP				80				156				83				158				81				79				81				78			
FUEL-FILTER-DIFF				.00				.02				.07				.07				.06				.06				.06				.05			
FUEL FLOW				56				102				119				136				153				169				179				192			
FUEL FLOW REF								102				119				135				152				168				178				191			
VIBRATION #1				.40				.20				.20				.20				.20				.20				.20				.20			
VIBRATION #2				.10				.20				.20				.20				.20				.20				.20				.20			
VIBRATION #3				.10				.10				.10				.10				.10				.10				.10				.10			
VIBRATION #4				.10				.00				.20				.20				.30				.30				.20				.20			

THIS ENGINE WILL PRODUCE RATED POWER AT 105.02% SPEED, 1404F/807C NGT/AND 93.5 PSI TORQUE AT STANDARD DAY SEA LEVEL COND.

TABLE 2. GAS TURBINE ENGINE TEST LOG SHEET (Continued)

RIN-102R3300242		PRINTED 11701790707 35 02 PAGE 2 OF 2	
SER.NO. RE403067B0D		SER.NO. 090Y.0021 REC.NO. 1 O/G S/N SAM	
CRV.SET	6 LIM.SET	P/C S/N CASE	FUEL MIL-J-5624 JP-4
		0.00 P12X	0.00 P12X
S/S START STOP START STOP START STOP		OIL MIL-L-23699 SPEC. GRAV. 0.80F .742	
NGT 1034	1100	1048	
ET 15.9	40.9	12.5	40.9 43.9
TOD 0741	0906	0928	1101 1611 1701
OS GOV CHECKS XN1 XN2 LOAD SHP MGT TOD ET			
GROUP CK	73.2	107.5	70 844 0647 11
DECAY CK	87.0	105.7	1000 101 1013
ACCEL CHECKS XN1 SECS MGT TOD ET			
FI TO	106.7	1.6	1250
FI TO	106.7	1.7	1265
T/O TO GI	3.0	923	
T/O TO GI	2.6	987	
POWER SETTING		NGRM.	
NGT	1140	1200	1300
SHAFT HORSE POWER	150	221	268
% VARIANCE	22.167	10.448	15.157
S.F.C. (WF/SHP)	.800	.787	.746
% VARIANCE	15.406	10.534	7.030
SHP	122	230	
SFC	.967	.778	
SEAL RUN-IN TIME .09			
OIL CONSUMPTION .000 PPH			
COMPR SEAL-VENT ORIFICE .02			
ANTI-ICE TUBES TEMP RISE 177			
LHV 18676			

TABLE 3. LEADING PARTICULARS

Dimensions	
Length	40.4 inches (1.03 m)
Height	22.5 inches (0.57 m)
Width	19.0 inches (0.48 m)
Engine weight (dry): T63-A-700	138.5 pounds (62.82 kgr.)
Maximum oil consumption	0.05 gal/hr (6.5 oz/hr)
Lubricating oil specifications	MIL-L-23699 or MIL-L-7808
Fuel specifications:	
Primary	MIL-T-5624 (JP-4)
Alternate	MIL-T-5624 (JP-5) (JP-8) (JET-A) (JETA-1)
Emergency	MIL-G-5572
Design power output	317 shp
Ram power rating	335 shp
Design speeds:	
Gas producer (N1)	100% (51,120 rpm)
Power turbine (N2)	100% (35,000 rpm)
Power output shaft	100% (6,000 rpm)

